

GUIDING LIGHT MONTESSORI, LLC

2041 OAK PARK BOULEVARD
PLEASANT HILL, CA

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: Jan 31, 2024



1 Important

Across 1 inspection since 2024, the issues cited most often were And Either Permanently Remove or Replace Outlet No Later Than 2/29/24 8 9 10 11 12 13 14 Per review,State Water Board Report Indicated There Was at Least One Outlet That Exceeded the Action Level Established by the State for Exposure. Faucet Is Located in the Outdoor Play Ground, Used for Hosing Down the Play Ground. This Posed a Potential Risk. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment. (1). The single finding was not critical.

Inspection Visits

Jan 31, 2024 1 Finding 1 Important

- **And Either Permanently Remove or Replace Outlet No Later Than 2/29/24 8 9 10 11 12 13 14 Per review,State Water Board Report Indicated There Was at Least One Outlet That Exceeded the Action Level Established by the State for Exposure. Faucet Is Located in the Outdoor Play Ground, Used for Hosing Down the Play Ground. This Posed a Potential Risk. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment.**
101700.3(b)(2) 1 2 3 4 5 6 7 Licensees shall maintain a lead value at or below the Action Level of 5 ppb in all outlets subject to the testing requirements of these Written...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.