

ENCHANTED LEARNING ACADEMY LLC

137 VIERSE DR
FARMINGTON, MO

1 Inspection Visit Since 2025 · 5 Findings

Most recent inspection: Dec 18, 2025

● 5 Important

Across 1 inspection since 2025, the issues cited most often were The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That the Bottom L-Shape Piece, Located at the Bottom of the Gate Was Cracked. (4) and The Door, Located Off the Art/music Area, Used as an Exit From the Facility Was Locked. (1). None of the 5 findings were critical.

Inspection Visits

Dec 18, 2025 5 Findings ● 5 Important

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That the Bottom L-Shape Piece, Located at the Bottom of the Gate Was Cracked.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That the Top of One Panel of Fencing Was Not Secure at the Top. This Was Located to the Left of the Castle.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That the Bottom L-Shape Piece, Located at the Bottom of the Gate Was Cracked.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That the Top of One Panel of Fencing Was Not Secure at the Top. This Was Located to the Left of the Castle.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Door, Located Off the Art/music Area, Used as an Exit From the Facility Was Locked.**

5 CSR 25-500.087 Fire Safety

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.