

BAYLESS SCHOOL DISTRICT

4531 WEBER RD
ST LOUIS, MO

2 Inspection Visits Since 2025 - 5 Findings

Most recent inspection: Apr 17, 2026

● 5 Important

Across 2 inspections since 2025, the issues cited most often were The Walls Located in the Orange Room Was/were Not in Good Condition as Evidenced by There Were Multiple Places Where the Paint Had Ripped Off the Wall Leaving Exposed Drywall and Additional Paint That Could Be Picked Off. There Were Spaces That Measured Approximately 1x1 Under the Window and 3x1 Ab (5). None of the 5 findings were critical.

Inspection Visits

Apr 17, 2026 2 Findings ● 2 Important

- **The Walls Located in the Orange Room Was/were Not in Good Condition as Evidenced by There Were Multiple Places Where the Paint Had Ripped Off the Wall Leaving Exposed Drywall and Additional Paint That Could Be Picked Off. There Were Spaces That Measured Approximately 1x1 Under the Window and 3x1 Ab**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Walls Located in the Orange Room Was/were Not in Good Condition as Evidenced by There Were Multiple Places Where the Paint Had Ripped Off the Wall Leaving Exposed Drywall and Additional Paint That Could Be Picked Off. There Were Spaces That Measured Approximately 1x1 Under the Window and 3x1 Ab**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

Jun 9, 2025 3 Findings ● 3 Important

- **The Walls Located in Green Room Was/were Not in Good Condition as Evidenced by a Small Missing Section of Paint Near Door.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Walls Located in Purple Room Was/were Not in Good Condition as Evidenced by a Small Missing Section of Paint Near Gathering Area.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

- **The Walls Located in Green Room Was/were Not in Good Condition as Evidenced by a Small Missing Section of Paint Near Door.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.