

ADVENTURES IN LEARNING

1109 CLARKE ST
DE SOTO, MO

2 Inspection Visits Since 2025 · 5 Findings

Most recent inspection: Nov 12, 2025

● 5 Important

Across 2 inspections since 2025, the issues cited most often were The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured 4.5 Inches, Specifically at the First & Second (4) and The Annual Sanitation Inspection Was Not Approved. (1). None of the 5 findings were critical.

Inspection Visits

Nov 12, 2025 4 Findings ● 4 Important

- The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured 4.5 Inches, Specifically at the First & Second

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That It Was Not Attached to the Top Rail, Specifically at the First & Second Panels Along the Right Run of The

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings That Were Between 3.5 and 9 Inches and Allow Entrapment - the Openings Measured 4.5 Inches, Specifically at the First & Second

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That It Was Not Attached to the Top Rail, Specifically at the First & Second Panels Along the Right Run of The

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

Sep 25, 2025 1 Finding ● 1 Important

● **The Annual Sanitation Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.