

HEAVENLY HEARTS

3400 MIAMI ST
ST LOUIS, MO

1 Inspection Visit Since 2026 - 5 Findings

Most recent inspection: Jan 21, 2026

● 5 Important

Across 1 inspection since 2026, the issues cited most often were The Walls Located in a Window in the Infant/toddler Room Was/were Not in Good Condition as Evidenced by There Were Three Chips Present in the Glass Pane That Lead Through to the Outside. The Chips Measured Approximately 1 Inch in Size. (2), Requirements for the Outdoor Play Area Were Not Met as Evidenced by the Fence Had Openings That Were Greater Than 3 1/2 Inches and Allow Entrapment - the Openings Measured 6 Inches Where a Fence Board Is Missing. (2), and The Premises Were Not Safe and Suitable as Evidenced by an Unused Freezer Without a Lock Was Being Stored in the Preschool Classroom. (1). None of the 5 findings were critical.

Inspection Visits

Jan 21, 2026 5 Findings ● 5 Important

- **The Premises Were Not Safe and Suitable as Evidenced by an Unused Freezer Without a Lock Was Being Stored in the Preschool Classroom.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1
- **The Walls Located in a Window in the Infant/toddler Room Was/were Not in Good Condition as Evidenced by There Were Three Chips Present in the Glass Pane That Lead Through to the Outside. The Chips Measured Approximately 1 Inch in Size.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1 (F)
- **The Walls Located a Window in the Preschool Room Was/were Not in Good Condition as Evidenced by There Was One Chip Present in the Glass Pane That Leads Through to the Outside. The Chip Measures Approximately 1 Inch in Size.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1 (F)
- **Requirements for the Outdoor Play Area Were Not Met as Evidenced by the Fence Had Openings That Were Greater Than 3 1/2 Inches and Allow Entrapment - the Openings Measured 6 Inches Where a Fence Board Is Missing.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 4 (A)

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by the Presence of Several Screws Sticking Out of Fence Boards.**

5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 4 (C)

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.