

MCKINLEY ELEMENTARY SCHOOL

601 4TH STREET
BAKERSFIELD, CA

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: Jan 31, 2024

1 Important

Across 1 inspection since 2024, the issues cited most often were During the Inspection of the Outside Play Area LPA Observed Several Areas That Needed to Be Addressed for Basic Maintenance and Upkeep Prior to Becoming a Safety Issue for the Children in Care. The Areas Discussed Were the Exposed Metal on the Play Structure Side Steps That Needs to Be Repainted/repared and LPA Observed Several Open Cracks on the Black Top of the Outdoor Play Area That Can Potentially Be a Tripping Hazard. LPA Advised That the Sand Box Needs to Be Raked Daily and Ensured That It Has a Cover. POC Due Date: 04/02/2024 (1). The single finding was not critical.

Inspection Visits

Jan 31, 2024 1 Finding 1 Important

- **During the Inspection of the Outside Play Area LPA Observed Several Areas That Needed to Be Addressed for Basic Maintenance and Upkeep Prior to Becoming a Safety Issue for the Children in Care. The Areas Discussed Were the Exposed Metal on the Play Structure Side Steps That Needs to Be Repainted/repared and LPA Observed Several Open Cracks on the Black Top of the Outdoor Play Area That Can Potentially Be a Tripping Hazard. LPA Advised That the Sand Box Needs to Be Raked Daily and Ensured That It Has a Cover. POC Due Date: 04/02/2024**

CCR 101238.2(d) Outdoor Activity Space (d) The surface of the outdoor activity space shall be maintained: This requirement is not met as evidenced by:

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.