

# MIDDLETOWN EARLY CONNECTION

15846 WARDLAW STREET  
MIDDLETOWN, CA

## 1 Inspection Visit Since 2023 - 1 Finding

Most recent inspection: Jan 30, 2023

● 1 Important

Across 1 inspection since 2023, the issues cited most often were . 8 9 10 11 12 13 14 Based on Record Review, Facility Drinking Fountains (Site “D”) Exceeded the Allowable Levels of Lead in the Water, Testing at 18 Ppb. This Is a Potential Health and Safety Risk to Children in Care. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment. (1). The single finding was not critical.

## Inspection Visits

Jan 30, 2023 1 Finding ● 1 Important

● . 8 9 10 11 12 13 14 Based on Record Review, Facility Drinking Fountains (Site “D”) Exceeded the Allowable Levels of Lead in the Water, Testing at 18 Ppb. This Is a Potential Health and Safety Risk to Children in Care. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment.

101700.3(b)(1) 1 2 3 4 5 6 7 101700.3(b)(1) A result with values of 5.0 ppb or greater shall be deemed an Action Level Exceedance. This requirement was not met as evidenced by: 1...

### About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.