

PENASQUITOS CHRISTIAN PRESCHOOL

14484 PENASQUITOS DRIVE
SAN DIEGO, CA

1 Inspection Visit Since 2022 · 1 Finding

Most recent inspection: Nov 1, 2022

1 Important

Across 1 inspection since 2022, the issues cited most often were Detailing the Faucet Procedures. 8 9 10 11 12 13 14 Based on Water Testing Results and Interviews, Facility Tested Over the Lead Exceedance Level at 4 Sink Faucet and Drinking Fountains Measuring at 17.000 Ppb , 7.400ppb, 6.700ppb, and 9.900. This Poses an Immediate/potential Health, Safety or Personal Rights Risk to Children in Care. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment. (1). The single finding was not critical.

Inspection Visits

Nov 1, 2022 1 Finding 1 Important

- **Detailing the Faucet Procedures. 8 9 10 11 12 13 14 Based on Water Testing Results and Interviews, Facility Tested Over the Lead Exceedance Level at 4 Sink Faucet and Drinking Fountains Measuring at 17.000 Ppb , 7.400ppb, 6.700ppb, and 9.900. This Poses an Immediate/potential Health, Safety or Personal Rights Risk to Children in Care. 8 9 10 11 12 13 14 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 1 2 3 4 5 6 7 Failure to Correct the Cited Deficiency(ies), on or Before the Plan of Correction (POC) Due Date, May Result in a Civil Penalty Assessment.**

1017000.3(b)(1) 1 2 3 4 5 6 7 101700.3(b)(1) Written Directives per AB2370: A result with values of 5.5 ppb or greater shall be deemed an Action Level Exceedance. This requirement...

About this report

Childery generates this report from public inspection records published by the California Department of Social Services, Community Care Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the California Department of Social Services, Community Care Licensing Division.