

ROSA ICELA SANTANA PERALTA

121 LURTON ST
NEW BRITAIN, CT

1 Inspection Visit Since 2025 · 5 Findings

Most recent inspection: Jul 22, 2025



● 5 Important

Across 1 inspection since 2025, the issues cited most often were 035-Carbon Monoxide Detector (4) and 057-Authorized Release (1). None of the 5 findings were critical.

Inspection Visits

Jul 22, 2025 5 Findings ● 5 Important

● **057-Authorized Release**

[19a-87b-10(b)(3)(A)]

● **034-Smoke Detectors**

[19a-87b-9(d)(6)]

● **035-Carbon Monoxide Detector**

[19a-87b-9(d)(7)]

● **036-Fire Extinguisher**

[19a-87b-9(d)(8)]

● **039-Safe Space-Sufficient**

[19a-87b-9(f)(1)]

About this report

Childery generates this report from public inspection records published by the Connecticut Office of Early Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Connecticut Office of Early Childhood.