

JOSEFINA LUIS

18 BLACKMAN RD
WATERBURY, CT

2 Inspection Visits Since 2024 · 5 Findings

Most recent inspection: Apr 28, 2025

● 5 Important

Across 2 inspections since 2024, the issues cited most often were 033-Emergency Evacuation Drills-Quarterly (4) and 021-Background Check (1). None of the 5 findings were critical.

Inspection Visits

Apr 28, 2025 1 Finding ● 1 Important

● **021-Background Check**

[19a-87b-8a]

Apr 16, 2024 4 Findings ● 4 Important

● **031-Stairways: Protected/Handrails**

[19a-87b-9(d)(4)(D)]

● **033-Emergency Evacuation Drills-Quarterly**

[19a-87b-9(d)(5)]

● **035-Carbon Monoxide Detector**

[19a-87b-9(d)(7)]

● **037-Auxilliary Heating System**

[19a-87b-9(d)(9)]

About this report

Childery generates this report from public inspection records published by the Connecticut Office of Early Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Connecticut Office of Early Childhood.