

Edmonson County Head Start

210 South Main Street, Suite 200
Brownsville, KY

2 Inspection Visits Since 2024 - 6 Findings

Most recent inspection: Mar 4, 2025

● 6 Important

Across 2 inspections since 2024, the issues cited most often were 922 KAR 2:120. Section 4. Premises Requirements.

(1) The Premises Shall Be:

- (a) Suitable for the Purpose Intended;
- (b) Kept Clean and in Good repair;

Findings:

General: Based on Observation and Interview, an Accumulation of Dust Was on the Ceiling Vent in Shared Restroom Between the Head Start and Early Head Start Rooms. (1), 922 KAR 2:120. Section 4. Premises Requirements.

(5) The Building Shall Be Constructed to Ensure The:

(a) Building is:

- 1. Dry;
- 2. Ventilated; and
- 3. Well Lit, Including Clean Light Fixtures That Are:
 - a. In Good Repair in All Areas; And
 - b. Shielded or Have Shatter-proof Bulbs Installed; And

(b) Following Are protected:

- 1. Windows;
- 2. Doors;
- 3. Stoves;
- 4. Heaters;
- 5. Furnaces;
- 6. Pipes; and
- 7. Stairs.

Findings:

General: Based on Observation and Interview, Dead Bugs Were in Two (2) Light Shields In (1), and 922 KAR 2:120. Section 12. Toilet, Diapering, and Toiletry Requirements.

(4) Each Toilet Shall:

- (a) Be Kept in Clean Condition;
- (b) Be Kept in Good Repair;
- (c) Be in a Lighted Room; And
- (d) Have Ventilation to Outside air.

Findings:

General: Based on Observation and Interview, a Toilet, Located Closest to the Head Start Room, Did Not Have Ventilation to Outside Air in the Restroom Located Between the Head Start And

About this report

Childery generates this report from public inspection records published by the Kentucky Cabinet for Health and Family Services, Division of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Kentucky Cabinet for Health and Family Services, Division of Child Care.

early Head Start rooms.
Hygienic Practices In Compliance (1). None of the 6 findings were critical.

Inspection Visits

Mar 4, 2025 4 Findings ● 4 Important

● **922 KAR 2:120. Section 4. Premises Requirements.**

(1) The Premises Shall Be:

(a) Suitable for the Purpose Intended;

(b) Kept Clean and in Good repair;

Findings:

General: Based on Observation and Interview, an Accumulation of Dust Was on the Ceiling Vent in Shared Restroom Between the Head Start and Early Head Start Rooms.

585 - Premises Requirements

● **922 KAR 2:120. Section 4. Premises Requirements.**

(5) The Building Shall Be Constructed to Ensure The:

(a) Building is:

1. Dry;

2. Ventilated; and

3. Well Lit, Including Clean Light Fixtures That Are:

a. In Good Repair in All Areas; And

b. Shielded or Have Shatter-proof Bulbs Installed; And

(b) Following Are protected:

1. Windows;

2. Doors;

3. Stoves;

4. Heaters;

5. Furnaces;

6. Pipes; and

7. Stairs.

Findings:

General: Based on Observation and Interview, Dead Bugs Were in Two (2) Light Shields In

605 - Building Requirements

About this report

Childery generates this report from public inspection records published by the Kentucky Cabinet for Health and Family Services, Division of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Kentucky Cabinet for Health and Family Services, Division of Child Care.

● **922 KAR 2:120. Section 12. Toilet, Diapering, and Toiletry Requirements.**

(4) Each Toilet Shall:

- (a) Be Kept in Clean Condition;**
- (b) Be Kept in Good Repair;**
- (c) Be in a Lighted Room; And**
- (d) Have Ventilation to Outside air.**

Findings:

General: Based on Observation and Interview, a Toilet, Located Closest to the Head Start Room, Did Not Have Ventilation to Outside Air in the Restroom Located Between the Head Start And early Head Start rooms.

Hygienic Practices In Compliance

695 - Toilet

● **922 KAR 2:120. Section 4. Premises Requirements.**

(20) An Outdoor Play Area Shall Be:

- (d) Safe From Foreseeable Hazard;**
- (e) Well Drained;**
- (f) Well Maintained;**
- (g) In Good Repair; And**
- (h) Visible to Staff at All times.**

Findings:

General: Based on Observation and Interview, Black Fabric Weed Block Was Raised Above the Protective Surface and Created a Tripping Hazard on the Preschool Playground.

795 - Playground Conditions

May 8, 2024 2 Findings ● 2 Important

● **922 KAR 2:090. Section 11. Staff Requirements.**

(16) In Accordance with KRS 199.896(15) and (16), a Staff Person with Supervisory Authority Over a Child Shall Complete the Following:

- (a) Six (6) Hours of Cabinet-approved Orientation Completed Within the First Three (3) Months of Employment in a Child-care Program;**
- (b) Nine (9) Hours of Cabinet-approved Early Care and Education Training Within the First Year of Employment in a Child Care Program, Including One and One-half (1 ½) Hours of Cabinet-a**

435 - Training

About this report

Childery generates this report from public inspection records published by the Kentucky Cabinet for Health and Family Services, Division of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Kentucky Cabinet for Health and Family Services, Division of Child Care.

- **922 KAR 2:120. Section 3. General Requirements.**
 - (7) The Following Shall Be Inaccessible to a Child in Care:**
 - (a) Toxic Cleaning Supplies, Poisons, and Insecticides;**
 - (b) Matches, Cigarettes, Lighters, and Flammable Liquids; And**
 - (c) Personal Belongings and Medications of staff.**

Findings:

General: Based on Observation, Two (2) Light Blue Tumbler Cups and a McDonald's Cup Belonged to Staff Members and Were Placed on a Shelf in the Head Start Room. These Items were Accessible to children.

Hygienic Pra

565 - Inaccessible Items

About this report

Childery generates this report from public inspection records published by the Kentucky Cabinet for Health and Family Services, Division of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Kentucky Cabinet for Health and Family Services, Division of Child Care.