

Monarch Montessori School

Asbury Road
Churchville, MD

1 Inspection Visit Since 2024 · 1 Finding

Most recent inspection: May 20, 2025



● 1 Important

Across 1 inspection since 2024, the issues cited most often were At the Time of the Inspection, the Stairs Leading From the Deck to the Play Area Has Cracked and Chipping Wood. (1). The single finding was not critical.

Inspection Visits

May 22, 2024 1 Finding ● 1 Important

- **At the Time of the Inspection, the Stairs Leading From the Deck to the Play Area Has Cracked and Chipping Wood.**

13A.16.05.12D

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.