

St. Mary School (Preschool)

Veirs Mill Road
Rockville, MD

1 Inspection Visit Since 2023 - 1 Finding

Most recent inspection: May 21, 2025

● 1 Important

Across 1 inspection since 2023, the issues cited most often were At Time of Inspection, LS Observed a Urinal in the Boys Bathroom (Second One From the Door) That Leaks After Flushing. Facility Is to Let the LS Know That It Has Been Repaired and LS Will Return to Follow Up. (1). The single finding was not critical.

Inspection Visits

Aug 9, 2023 1 Finding ● 1 Important

- **At Time of Inspection, LS Observed a Urinal in the Boys Bathroom (Second One From the Door) That Leaks After Flushing. Facility Is to Let the LS Know That It Has Been Repaired and LS Will Return to Follow Up.**

13A.16.05.01A(1)

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.