

Sheina Rivkin

Aigburth Road
Towson, MD

2 Inspection Visits Since 2025 - 14 Findings

Most recent inspection: Nov 13, 2025

● 14 Important

Across 2 inspections since 2025, the issues cited most often were LS Observed That There Are Bird Barbs on the Playset, There Is a Tree/bush Less Than 6 Ft Behind the Swings, and There Needs to Be Padding Under the Swings. (2), LS Observed That There Is a Lack of Science Materials. (1), and LS Observed That There Are Only 7 Cots and They Need 2 More to Be Licensed for 9 Preschoolers. (1). None of the 14 findings were critical.

Inspection Visits

Nov 13, 2025 3 Findings ● 3 Important

● **LS Observed That There Are Bird Barbs on the Playset, There Is a Tree/bush Less Than 6 Ft Behind the Swings, and There Needs to Be Padding Under the Swings.**

13A.18.05.12D

● **LS Observed That There Is a Lack of Science Materials.**

13A.18.09.03B(1)

● **LS Observed That There Are Only 7 Cots and They Need 2 More to Be Licensed for 9 Preschoolers.**

13A.18.09.04A(1)

Aug 26, 2025 11 Findings ● 11 Important

● **LS Observed the Staffing Pattern Was Not Posted.**

13A.18.03.05B

● **There Was a Hole in the Wall and Exposed Wiring on the Lower Level.**

13A.18.05.01B

● **LS Observed That There Was a Hole in the Wall and a Corner of the Wall Was Chipping.**

13A.18.05.04

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.

- **The Water Temperature Was 130 Degrees.**
13A.18.05.07A
- **Diapering Area Is Not Near the Sink.**
13A.18.05.08B
- **There Was No Toilet Paper, Trash Can Liner or Paper Towels in the Bathroom on the First Level.**
13A.18.05.08E
- **There Is a Trampoline That Does Not Have a Lock on It and Is Accessible to Children, an Open Fence with Access to the Front Yard and a Shed with Hazards in It. There Were Many Plants, Trees and Grasses That Create a Hazard. There Was a Holly Bush with Berries on It That Is at the Entrance to the Chi**
13A.18.05.12D
- **The Swing Set Has Rotting Wood and Is Splintering, the S Hooks Need to Be Closed and There Are Broken Toys Laying Around.**
13A.18.05.12E
- **The Outdoor Area Is Not Fully Enclosed, a Piece of Fence Is Missing on the Left Side Where the Shed Is, and Behind the Swing Set.**
13A.18.05.12F
- **The Trampoline Is Accessible to Children.**
13A.18.05.12I(2)
- **LS Observed That the Director and Substitute Did Not Have Completed Orientations in Their Files.**
13A.18.06.02

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.