

Wisdom Childcare Center

Old Montgomery Rd
Columbia, MD

4 Inspection Visits Since 2025 · 14 Findings

Most recent inspection: Mar 19, 2026

● 14 Important

Across 4 inspections since 2025, the issues cited most often were LS Did Not Observe Paper Towels Available at a Sink Within Reach of Children's Use. (2), LS Did Not Observe Tightly Fitting Sheets for All Mattresses and One Mattress Was Observed with a Tear. (2), and Facility Is Requesting Approval for 15 School Age Children. LS Observed 6 Chairs. Facility Must Provide a Sufficient Quantity of Furnishings and Equipment According to the Numbers, Ages, and Development Needs of the Children. (1). None of the 14 findings were critical.

Inspection Visits

Mar 19, 2026 2 Findings ● 2 Important

● **LS Did Not Observe Paper Towels Available at a Sink Within Reach of Children's Use.**

13A.16.05.08J

● **LS Did Not Observe Tightly Fitting Sheets for All Mattresses and One Mattress Was Observed with a Tear.**

13A.16.09.04A(4)(a)

Mar 13, 2026 3 Findings ● 3 Important

● **Facility Is Requesting Approval for 15 School Age Children. LS Observed 6 Chairs. Facility Must Provide a Sufficient Quantity of Furnishings and Equipment According to the Numbers, Ages, and Development Needs of the Children.**

13A.16.09.03A

● **LS Did Not Observe Tight Fitting Sheets on All Cribs in the Facility. Facility Must Replace All Sheets in the Facility.**

13A.16.09.04A(4)(a)

● **LS Observed One Torn Mattress in the Infant Room. Facility Must Replace the Old Mattress with a New Mattress That Meets the Standards of the U.S. Consumer Product Safety Commission.**

13A.16.09.04C

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.

Feb 27, 2026 8 Findings ● 8 Important

- **LS Did Not Observe a Working Light in the Boiler Room.**
13A.16.05.01B
- **The Ventilation in the Basement Does Not Appear to Be Operating Sufficiently Enough to Provide an Adequate Exchange of Air to Protect a Child's Health and Comfort.**
13A.16.05.06
- **LS Did Not Observe Cup Dispensers Near the Drinking Water Coolers. Facility Must Ensure That Children Have Free Access to Water Without the Assistance of an Adult.**
13A.16.05.07B
- **LS Did Not Observe Paper Towels in Each Bathroom.**
13A.16.05.08I
- **LS Did Not Observe Sanitary Supplies That Are Available Within the Reach of a Child Capable of Using the Toilet Unassisted.**
13A.16.05.08J
- **LS Observed the Basement Classroom. The Entire Classroom, Kitchen and Bathroom Is in Need of a Deep Cleaning. The Carpet in the Infant Room Needs to Be Cleaned.**
13A.16.05.11A
- **LS Observed Bleach and Soap in an Unlocked Cabinet in the Infant Room. The Bleach Was Removed During the Inspection.**
13A.16.10.04A
- **LS Observed Several Outlets with Missing Safety Caps Throughout the Facility.**
13A.16.10.04F

Nov 6, 2025 1 Finding ● 1 Important

- **The Complainant States That There Are Nails Sticking Out Under the Deck, the Lock on the Playground Is Broken, the Swing Is Worn Out, and Wires Coming Out of the AC Unit Outside by the Playground. LS Observed a Swing That Has Cracks in the Seat and Is in Need of Repair and Wires Hanging on the Side**
13A.16.05.12D

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.