

Dream Child Development Center

Ritchie Road

Capitol Heights, MD

1 Inspection Visit Since 2025 · 2 Findings

Most recent inspection: Sep 23, 2025

● 2 Important

Across 1 inspection since 2025, the issues cited most often were The Furnace Doors Are Broken and Must Be Replaced. (1) and Observed 2 Sinks in the Proposed Infant Room Water Temperature Registering at 125 Degrees. Adjustments Are Required. (1). None of the 2 findings were critical.

Inspection Visits

Sep 9, 2025 2 Findings ● 2 Important

● The Furnace Doors Are Broken and Must Be Replaced.

13A.16.05.01A(1)

● Observed 2 Sinks in the Proposed Infant Room Water Temperature Registering at 125 Degrees. Adjustments Are Required.

13A.16.05.07A

About this report

Childery generates this report from public inspection records published by the Maryland State Department of Education, Office of Child Care. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Maryland State Department of Education, Office of Child Care.