

# ABC PRESCHOOL

1950 ROLLING HILLS DR  
JEFFERSON CITY, MO

## 3 Inspection Visits Since 2025 - 5 Findings

Most recent inspection: Feb 6, 2026



● 5 Important

Across 3 inspections since 2025, the issues cited most often were The Annual Fire Safety Inspection Was Not Approved. (4) and Requirements of 19 CSR 30-62.087 Fire Safety Were Not Met as Evidenced by the Disaster and Tornado Drill Was Not Held at Least One Time Every Three Months. (1). None of the 5 findings were critical.

## Inspection Visits

**Feb 6, 2026** 2 Findings ● 2 Important

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

**Dec 8, 2025** 2 Findings ● 2 Important

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

**Jul 29, 2025** 1 Finding ● 1 Important

● **Requirements of 19 CSR 30-62.087 Fire Safety Were Not Met as Evidenced by the Disaster and Tornado Drill Was Not Held at Least One Time Every Three Months.**

5 CSR 25-500.087 Fire Safety

### About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.