

CREATIVE KIDS CHILD DEVELOPMENT

1408 N KINGSHIGHWAY
ST LOUIS, MO

2 Inspection Visits Since 2026 - 5 Findings

Most recent inspection: Apr 22, 2026

● 5 Important

Across 2 inspections since 2026, the issues cited most often were Diapering Requirements Were Not Met as Evidenced by the Diapering Table Was Not Safe in That One Diapering Table Located in the Infant/toddler Space and One Diapering Table in the Three's Room Were Wobbly and Unstable. (5). None of the 5 findings were critical.

Inspection Visits

Apr 22, 2026 4 Findings ● 4 Important

- **Diapering Requirements Were Not Met as Evidenced by the Diapering Table Was Not Safe in That One Diapering Table Located in the Infant/toddler Space and One Diapering Table in the Three's Room Were Wobbly and Unstable.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings Large Enough for a Child to Crawl or Fall Through - the Openings Measured Approximately 5' 2".**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **Diapering Requirements Were Not Met as Evidenced by the Diapering Table Was Not Safe in That One Diapering Table Located in the Infant/toddler Space and One Diapering Table in the Three's Room Were Wobbly and Unstable.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings Large Enough for a Child to Crawl or Fall Through - the Openings Measured Approximately 5' 2".**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

Mar 6, 2026 1 Finding ● 1 Important

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

- **The Requirements for Protective Outlet Covers or Twist-lock Outlets Were Not Met as Evidenced by Electrical Outlets Were Not Covered in That Eight Outlets Were Unplugged in an Infant Classroom, and Two Outlets Were Uncovered in a Preschool Room.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.