

YOUTH IN NEED

302 KUHL AVE
WARRENTON, MO

3 Inspection Visits Since 2024 · 5 Findings

Most recent inspection: Oct 17, 2025

● 5 Important

Across 3 inspections since 2024, the issues cited most often were The Annual Fire Safety Inspection Was Not Approved. (4) and Requirements of 19 CSR 30-62.087 Fire Safety Were Not Met as Evidenced by the Disaster and Tornado Drill Record Was Not Available on the Premises. (1). None of the 5 findings were critical.

Inspection Visits

Oct 17, 2025 2 Findings ● 2 Important

● **The Annual Fire Safety Inspection Was Not Approved.**
5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Approved.**
5 CSR 25-500.052 Annual Requirements

May 14, 2025 2 Findings ● 2 Important

● **The Annual Fire Safety Inspection Was Not Approved.**
5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Approved.**
5 CSR 25-500.052 Annual Requirements

Jun 3, 2024 1 Finding ● 1 Important

● **Requirements of 19 CSR 30-62.087 Fire Safety Were Not Met as Evidenced by the Disaster and Tornado Drill Record Was Not Available on the Premises.**
5 CSR 25-500.087 Fire Safety

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.