

TOMLIN ACADEMY LLC

9700 HOLMES RD
KANSAS CITY, MO

2 Inspection Visits Since 2025 - 5 Findings

Most recent inspection: Nov 13, 2025

● 5 Important

Across 2 inspections since 2025, the issues cited most often were The Annual Fire Safety Inspection Was Not Approved. (3) and The Floors Located Room S105 Was/were Not in Good Condition as Evidenced by the Carpet Strip Was Missing in the Door Jam. (2). None of the 5 findings were critical.

Inspection Visits

Nov 13, 2025 4 Findings ● 4 Important

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

● **The Floors Located Room S105 Was/were Not in Good Condition as Evidenced by the Carpet Strip Was Missing in the Door Jam.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

● **The Floors Located Room S105 Was/were Not in Good Condition as Evidenced by the Carpet Strip Was Missing in the Door Jam.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

Oct 8, 2025 1 Finding ● 1 Important

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.