

HOPE LEARNING CENTER

9 LOVE PARK LN
WENTZVILLE, MO

2 Inspection Visits Since 2024 · 5 Findings

Most recent inspection: Aug 1, 2025

● 5 Important

Across 2 inspections since 2024, the issues cited most often were The Walls Located 2-K Bathroom Was/were Not in Good Condition as Evidenced by Peeling Paint.. (3) and Emergency Numbers for the Police, Fire Department, Poison Control, and Ambulance Were Not Posted. (2). None of the 5 findings were critical.

Inspection Visits

Aug 1, 2025 2 Findings ● 2 Important

- **Emergency Numbers for the Police, Fire Department, Poison Control, and Ambulance Were Not Posted.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 2 (D)
- **Emergency Numbers for the Police, Fire Department, Poison Control, and Ambulance Were Not Posted.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 2 (D)

Sep 11, 2024 3 Findings ● 3 Important

- **The Walls Located 2-K Bathroom Was/were Not in Good Condition as Evidenced by Peeling Paint..**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1 (F)
- **The Ceilings Located Infant Room Was/were Not in Good Condition as Evidenced by Water Damage on Tiles.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1 (F)
- **The Ceilings Located 2-K Was/were Not in Good Condition as Evidenced by Water Damage.**
5 CSR 25-300.090 Physical Plant, Space, Supplies and Equipment 1 (F)

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.