

OZARK ACTION, INC.

1402 E US HIGHWAY 60
MOUNTAIN VIEW, MO

1 Inspection Visit Since 2025 · 5 Findings

Most recent inspection: Oct 17, 2025

● 5 Important

Across 1 inspection since 2025, the issues cited most often were The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by Broken Wooden Lattice Work at the Base of the Storage Shed Accessible to the Children, This Is Creating Openings Over 3 1/2 Inches and Sharp Edges. Also the Large Bolts Holding the Black Plastic Barrier Around the R (4) and Stationary Equipment, Basket Ball Goal, Was Unsafe as Evidenced by the Equipment Had Exposed Footings. (1). None of the 5 findings were critical.

Inspection Visits

Oct 17, 2025 5 Findings ● 5 Important

- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by Broken Wooden Lattice Work at the Base of the Storage Shed Accessible to the Children, This Is Creating Openings Over 3 1/2 Inches and Sharp Edges. Also the Large Bolts Holding the Black Plastic Barrier Around the R**
5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers
- **The Observed Surface Area Under Swings, From Which a Child Might Fall Consists of Bare Soil.**
5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers
- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by Broken Wooden Lattice Work at the Base of the Storage Shed Accessible to the Children, This Is Creating Openings Over 3 1/2 Inches and Sharp Edges. Also the Large Bolts Holding the Black Plastic Barrier Around the R**
5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers
- **The Observed Surface Area Under Swings, From Which a Child Might Fall Consists of Bare Soil.**
5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers
- **Stationary Equipment, Basket Ball Goal, Was Unsafe as Evidenced by the Equipment Had Exposed Footings.**
5 CSR 25-500.092 Furniture, Equipment and Materials

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.