

PRE-K UNIVERSITY LLC

3327 N HANLEY RD
ST LOUIS, MO

1 Inspection Visit Since 2026 - 5 Findings

Most recent inspection: Mar 25, 2026

● 5 Important

Across 1 inspection since 2026, the issues cited most often were The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by Three Openings in the Lattice Under the Deck on the Outdoor Play Space. Two Openings Measured Approximately 12 Inches by 7 Inches. The Other Opening Measured Approximately 23 Inches by 20 Inches. (2), The Annual Fire Safety Inspection Was Not Approved. (1), and Outdoor Equipment, Two Bikes, in the Playground Space Was Not in Good Condition as Evidenced by There Were Broken Sections of Plastic Along the Front and Back of the Bike. The Seat on One Bike Was Broken. (1). None of the 5 findings were critical.

Inspection Visits

Mar 25, 2026 5 Findings ● 5 Important

● **The Annual Fire Safety Inspection Was Not Approved.**

5 CSR 25-500.052 Annual Requirements

● **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by Three Openings in the Lattice Under the Deck on the Outdoor Play Space. Two Openings Measured Approximately 12 Inches by 7 Inches. The Other Opening Measured Approximately 23 Inches by 20 Inches.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

● **The Fall-zone Area Under and Around Outdoor Equipment Where Children Might Fall and Be Injured Was Not Covered with Impact-absorbing Materials to Cushion a Fall as Evidenced by No Resilient Material Was Present.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

● **Outdoor Equipment, Two Bikes, in the Playground Space Was Not in Good Condition as Evidenced by There Were Broken Sections of Plastic Along the Front and Back of the Bike. The Seat on One Bike Was Broken.**

5 CSR 25-500.092 Furniture, Equipment and Materials

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

- **The Requirements for Obtaining 12 Clock Hours Each Calendar Year Were Not Met. For the Calendar Year of 2024, the Staff Listed Need the Following Information: Brandi Barker Needs 2.5 Hours and Kenya Stevens Needs 12 Hours. As of March 25, 2026, Kenya Stevens Needs 12 Hours.**

5 CSR 25-500.102 Personnel

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.