

SOUTHSIDE EARLY CHILDHOOD CENTER

3740 MARINE AVE
ST LOUIS, MO

1 Inspection Visit Since 2026 - 5 Findings

Most recent inspection: Apr 16, 2026

● 5 Important

Across 1 inspection since 2026, the issues cited most often were The Requirements for Protective Outlet Covers or Twist-lock Outlets Were Not Met as Evidenced by Electrical Outlets Were Not Covered in That in the Moon and Galaxy Classroom Were Missing Outlet Covers. (4) and The Facility Was Observed Using an Extension Cord in All of the Classrooms That Are Connected to a Portable Air Conditioning Unit. (1). None of the 5 findings were critical.

Inspection Visits

Apr 16, 2026 5 Findings ● 5 Important

- **The Requirements for Protective Outlet Covers or Twist-lock Outlets Were Not Met as Evidenced by Electrical Outlets Were Not Covered in That in the Moon and Galaxy Classroom Were Missing Outlet Covers.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **Hazardous Items as Follows Were Accessible to Children: Wires From a Portable Ac Unit Were Accessible to Children. The Item(s) Was/were Located the Moon Classroom.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Had Openings Large Enough for a Child to Crawl or Fall Through - the Openings Measured Eight Inches in Height by Twelve Inches Wide at the B**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Requirements for Protective Outlet Covers or Twist-lock Outlets Were Not Met as Evidenced by an Electrical Plate Was Missing in That Therer Is a Missing Electric Plate in the Galaxy Classroom Next to the Window.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Was Observed Using an Extension Cord in All of the Classrooms That Are Connected to a Portable Air Conditioning Unit.**

5 CSR 25-500.087 Fire Safety

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.