

KINDER KARE

103 MYERS ST
LICKING, MO

1 Inspection Visit Since 2025 · 5 Findings

Most recent inspection: Mar 5, 2025

● 5 Important

Across 1 inspection since 2025, the issues cited most often were A Stairwell with a Drop-off of More Than 24 Inches Had a Railing/barrier Was Not Constructed Safely as Evidenced by the Wires Were Exposed Causing Potential Cutting Hazard and the Rail Was Not Tight Allowing for a Fall. (5). None of the 5 findings were critical.

Inspection Visits

Mar 5, 2025 5 Findings ● 5 Important

- **A Stairwell with a Drop-off of More Than 24 Inches Had a Railing/barrier Was Not Constructed Safely as Evidenced by the Wires Were Exposed Causing Potential Cutting Hazard and the Rail Was Not Tight Allowing for a Fall.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Walls Located Door Trim in Blue Room and Both Vanities in the Bathrooms and Trim Around the Closet with Cubbies Was/were Not in Good Condition as Evidenced by Broken or Missing.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **There Was Evidence of Dirt/debris in in the Vents Above the Door Way Into the Hall and Vents Into the Furnace Room.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility Did Not Have a Fenced Outdoor Play Area That Was on or Adjoining the Day Care Property and Was Accessible Without Hazard as Evidenced by the Fence Was Not in Good Condition in That Fence Fasteners Were Missing on Several Posts Allowing the Fence Not to Be Secured .**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

- **The Facility's Outdoor Space Was Not Safe for Children's Activities as Evidenced by There Were Two Railway Ties That Were Broken Causing a Tripping Hazzard.**

5 CSR 25-500.082 Physical Requirements of Group Day Care Homes and Day Care Centers

About this report

Childery generates this report from public inspection records published by the Missouri Department of Elementary and Secondary Education, Office of Childhood. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Missouri Department of Elementary and Secondary Education, Office of Childhood.