

NORTHEAST ELEMENTARY SCHOOL

4665 NC HWY 111 NORTH
PIKEVILLE, NC

3 Inspection Visits Since 2024 · 5 Findings · 0% Corrected at Visit

Most recent inspection: Jan 6, 2026

● 5 Important

Across 3 inspections since 2024, the issues cited most often were A Safe Indoor and Outdoor Environment Was Not Provided for the Children. (1), All Corrosive Agents, Pesticides, Bleaches, Detergents, Cleansers, Polishes, Any Product Which Is Under Pressure in an Aerosol Dispenser, and Any Substance... (1), and Monthly Playground Inspections Were Not Completed And/or They Were Not Completed by an Individual Trained in Playground Safety Requirements. (1). None of the 5 findings were critical.

Inspection Visits

Jan 6, 2026 2 Findings ● 2 Important

● A Safe Indoor and Outdoor Environment Was Not Provided for the Children.

In the outdoor environment, a wooden bench was cracked causing a pinching hazard. A plastic play house structure has cracks forming and holes that had sharp edges. Violation confirmed corrected by letter received

● All Corrosive Agents, Pesticides, Bleaches, Detergents, Cleansers, Polishes, Any Product Which Is Under Pressure in an Aerosol Dispenser, and Any Substance...

which may be hazardous to a child if ingested, inhaled, or handled were not stored in a locked room or cabinet. A closet door was

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

Jan 8, 2025 2 Findings ● 2 Important

● **Monthly Playground Inspections Were Not Completed And/or They Were Not Completed by an Individual Trained in Playground Safety Requirements.**

The required playground inspection for the month of September was not completed. Violation confirmed corrected by letter received from provider

● **Health and Safety Training Topics Were Not Included as Part of On-going Training Within Five Years of Completing the Previous Health and Safety Training Topics.**

For staff member J. Seabrooks, all of the Health and Safety topics were not included as part of the on-going training within

Jan 11, 2024 1 Finding ● 1 Important

● **Electrical Outlets and Power Strips, Not in Use, Which Were Located in Space Used by Children Did Not Have Safety Outlets or Were Not Covered with Safety Plugs...**

unless located behind furniture or equipment that cannot be moved by a child. A power strip, located under the computer table

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.