

INDIAN TRAIL ELEMENTARY

200 EDUCATION ROAD

INDIAN TRAIL, NC

2 Inspection Visits Since 2025 · 5 Findings · 20% Corrected at Visit

Most recent inspection: Feb 17, 2026

● 5 Important

Across 2 inspections since 2025, the issues cited most often were Electrical Outlets and Power Strips, Not in Use, Which Were Located in Space Used by Children Did Not Have Safety Outlets or Were Not Covered with Safety Plugs... (2), A Current Activity Plan Was Not Posted for Each Group of Children for Reference. (1), and Operator Has Not Scheduled and Obtained a Fire Inspection Within 12 Months of the Previous Inspection. (1). None of the 5 findings were critical.

Inspection Visits

Feb 17, 2026 2 Findings ● 2 Important

● **A Current Activity Plan Was Not Posted for Each Group of Children for Reference.**

In space #140, they did not have their own current lesson plan posted; I observed copies of lesson plans from space #142 dating from the month of 1/2026. The lesson plan posted did not belong to this space

● **Electrical Outlets and Power Strips, Not in Use, Which Were Located in Space Used by Children Did Not Have Safety Outlets or Were Not Covered with Safety Plugs...**

unless located behind furniture or equipment that cannot be moved by a child. In space #140, I observed a set of outlets uncovered

Nov 20, 2025 3 Findings ● 3 Important

● **Operator Has Not Scheduled and Obtained a Fire Inspection Within 12 Months of the Previous Inspection.**

Operator did not submit the original approved report to DCDEE within one week of the inspection visit on a form provided by the Division. The program's last fire inspection on file was

● **Diaper Changing Surfaces Were Not Kept Free of Storage.**

In the boy's bathroom the diaper changing table had posters and items on top of the surface. Violation corrected during visit

Corrected at visit

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

● **Electrical Outlets and Power Strips, Not in Use, Which Were Located in Space Used by Children Did Not Have Safety Outlets or Were Not Covered with Safety Plugs...**

unless located behind furniture or equipment that cannot be moved by a child. In space #142, two (2) outlets were uncovered.

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.