

EXCEL LEARNING CENTERS #III

700 NORTH 35TH STREET
MOREHEAD CITY, NC

3 Inspection Visits Since 2025 · 5 Findings · 0% Corrected at Visit

Most recent inspection: May 28, 2026

● 5 Important

Across 3 inspections since 2025, the issues cited most often were The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment. (3), The Trained Staff Did Not Review the EPR Plan Annually or When Information in the Plan Changed to Ensure All Information Was Current. (1), and All Equipment and Furnishings Were Not in Good Repair. (1). None of the 5 findings were critical.

Inspection Visits

May 28, 2026 1 Finding ● 1 Important

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The depth of the mulch under the large swing set on the preschool outdoor space was not nine (9) inches. Violation pending provider response

Dec 22, 2025 2 Findings ● 2 Important

● **The Trained Staff Did Not Review the EPR Plan Annually or When Information in the Plan Changed to Ensure All Information Was Current.**

The last date the EPR Plan was updated is June 11, 2024. The facility's EPR Plan does not have current administrator information. Violation confirmed c

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The depth of the mulch in outdoor space #1 under the large swing set was not nine (9) inches. Violation confirmed corrected by letter received from provider on 1/5/2026

Jun 25, 2025 2 Findings ● 2 Important

● **All Equipment and Furnishings Were Not in Good Repair.**

The large light blue bench in outdoor space one (1) has chipped paint and splintering wood. Violation confirmed corrected by letter received from provider on 7/8/2025

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The depth of the mulch in outdoor space one (1) under the large swings was not nine (9) inches. Violation confirmed corrected by letter received from provider on 7/8/2025

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.