

## THE GROWING YEARS

1700 BENJAMIN PARKWAY  
GREENSBORO, NC

### 2 Inspection Visits Since 2025 - 5 Findings - 0% Corrected at Visit

Most recent inspection: Oct 8, 2025

● 5 Important

Across 2 inspections since 2025, the issues cited most often were A Safe Indoor and Outdoor Environment Was Not Provided for the Children. (2), All Stationary Equipment, More Than 18 Inches High, Was Not Installed Over Protective Surfacing. (1), and All Equipment and Furnishings Were Not in Good Repair. (1). None of the 5 findings were critical.

### Inspection Visits

**Oct 8, 2025** 4 Findings ● 4 Important

- **All Stationary Equipment, More Than 18 Inches High, Was Not Installed Over Protective Surfacing.**  
The mulch on the front playground did not meet the required depth. The mulch was less than one inch at the bottom of the slide. Violation confirmed corrected by letter received from prov
- **All Equipment and Furnishings Were Not in Good Repair.**  
On the playground for two and three year children two metal car structure bench the paint is peeling. Violation confirmed corrected by letter received from provider on 10/21/2025
- **A Safe Indoor and Outdoor Environment Was Not Provided for the Children.**  
The wooden boards around the edge of the mulch were split. There were several roots that were not painted to alert the children of caution to eliminate a tripping hazard and a stump with sharp edges which is
- **Leftover Medicines Were Not Returned to the Parent After the Course of Treatment Was Completed, After Authorization Was Withdrawn or After Authorization Had...**  
expired and/or medication was not discarded within 72 hours of completion of treatment or withdrawal of authorization. There wa

#### About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

**Apr 3, 2025** 1 Finding ● 1 Important

● **A Safe Indoor and Outdoor Environment Was Not Provided for the Children.**

On the playground for two-year-olds, the concrete securing the post for the canopy was visible. The base of the concrete steps had jagged and sharp edges. Violation confirmed corrected by letter received from pro

**About this report**

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.