

KINDERCARE LEARNING CENTER

760 RIVERSIDE DRIVE
MOUNT AIRY, NC

1 Inspection Visit Since 2025 · 5 Findings · 0% Corrected at Visit

Most recent inspection: Dec 4, 2025

● 5 Important

Across 1 inspection since 2025, the issues cited most often were All Walls and Ceilings Including Doors and Windows Were Not Kept Clean, Free of Visible Fungal Growth, and in Good Repair. (1), Swings Did Not Have Surfacing That Extends Two Times the Length of the Pivot Point to the Surface Below Beyond the External Limits of the Equipment. (1), and A Safe Indoor and Outdoor Environment Was Not Provided for the Children. (1). None of the 5 findings were critical.

Inspection Visits

Dec 4, 2025 5 Findings ● 5 Important

● **All Walls and Ceilings Including Doors and Windows Were Not Kept Clean, Free of Visible Fungal Growth, and in Good Repair.**

In space 3A/B, a wall tile was missing in the girl's restroom exposing crumbling sheetrock. Violation confirmed corrected by letter received from provider on 12/1

● **Swings Did Not Have Surfacing That Extends Two Times the Length of the Pivot Point to the Surface Below Beyond the External Limits of the Equipment.**

Mulch at the swings on playground two measured three inches and did not extend two times the length of the pivot point. Violation confir

● **A Safe Indoor and Outdoor Environment Was Not Provided for the Children.**

On playground 2 loose weed block fabric presented a tripping hazard near the end of the building. Violation confirmed corrected by letter received from provider on 12/17/2025

● **All Corrosive Agents, Pesticides, Bleaches, Detergents, Cleansers, Polishes, Any Product Which Is Under Pressure in an Aerosol Dispenser, and Any Substance...**

which may be hazardous to a child if ingested, inhaled, or handled were not stored in a locked room or cabinet. Two aerosol cans

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

- **A Child Care Operator Did Not Notify the Division of Any New Child Care Providers, as Defined in G.S. 110-90.2(a)(2), Who Were Hired or Moved Into the Child...**

care facility within five business days. A center roster has not been created in ABCMS. Violation confirmed corrected by letter

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.