

# BLESSED BEGINNINGS

8410 SHIREDALE LANE  
CHARLOTTE, NC

## 2 Inspection Visits Since 2024 - 5 Findings - 100% Corrected at Visit

Most recent inspection: Jun 3, 2025

● 5 Important

Across 2 inspections since 2024, the issues cited most often were Electrical Outlets Not in Use Were Not Covered. (1), Outdoor Stationary Play Equipment Was Not Anchored And/or Equipment Was Installed Over Concrete or Asphalt. (1), and The Child Care Operator Did Not Comply with All State Laws, Federal Laws And/or Local Ordinances That Pertain to Child Health, Safety, and Welfare, as Required... (1). None of the 5 findings were critical.

## Inspection Visits

**Jun 3, 2025** 1 Finding ● 1 Important

● **Electrical Outlets Not in Use Were Not Covered.**

A outlet cover on the wall near the bathroom did not have the appropriate covering. Violation corrected during visit

Corrected at visit

**Oct 22, 2024** 4 Findings ● 4 Important

● **Outdoor Stationary Play Equipment Was Not Anchored And/or Equipment Was Installed Over Concrete or Asphalt.**

Equipment was not anchored and posed a potential hazard due to the proximity to the fence. Violation corrected during visit

Corrected at visit

● **The Child Care Operator Did Not Comply with All State Laws, Federal Laws And/or Local Ordinances That Pertain to Child Health, Safety, and Welfare, as Required...**

by General Statute 110-91. The fenced measured under 48 inches in several spaces. Violation corrected during visit

Corrected at visit

### About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

● **Openings in Equipment, Steps, Decks, and Handrails Were Not Smaller Than 3 1/2 Inches or Greater Than 9 Inches to Prevent Entrapment.**

Several sections of the fence where the sides met measured 3.5 inches up to 6.0 inches. Violation corrected during visit

Corrected at visit

● **Telephone Numbers for the Fire Department, Law Enforcement Office, Emergency Medical Service, and Poison Control Were Not Posted in a Location Visible in The...**

home. This document could not be located as being posted. Violation corrected during visit

Corrected at visit

**About this report**

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.