

THE SUNSHINE HOUSE #148

324 TEAL DRIVE
RAEFORD, NC

1 Inspection Visit Since 2025 · 2 Findings · 0% Corrected at Visit

Most recent inspection: Dec 3, 2025

● 2 Important

Across 1 inspection since 2025, the issues cited most often were All Equipment and Furnishings Were Not in Good Repair. (1) and The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment. (1). None of the 2 findings were critical.

Inspection Visits

Dec 3, 2025 2 Findings ● 2 Important

● **All Equipment and Furnishings Were Not in Good Repair.**

The composite structure on the preschool playground contained multiple areas that were cracked and peeling on the platforms and stairs. Bolts were rusted. Violation confirmed corrected by letter received from provider on 12/23/202

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The sand used as resilient surfacing was less than 6 inches under the swings and the composite structure. Violation confirmed corrected by letter received from provider on 12/23/2025

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.