

KINDERCARE LEARNING CENTER

850 JOHNSON RIDGE ROAD
ELKIN, NC

2 Inspection Visits Since 2025 · 5 Findings · 0% Corrected at Visit

Most recent inspection: Mar 17, 2026

● 5 Important

Across 2 inspections since 2025, the issues cited most often were Monthly Playground Inspections Were Not Completed And/or They Were Not Completed by an Individual Trained in Playground Safety Requirements. (1), The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment. (1), and All Walls and Ceilings Including Doors and Windows Were Not Kept Clean, Free of Visible Fungal Growth, and in Good Repair. (1). None of the 5 findings were critical.

Inspection Visits

Mar 17, 2026 2 Findings ● 2 Important

● **Monthly Playground Inspections Were Not Completed And/or They Were Not Completed by an Individual Trained in Playground Safety Requirements.**

The last playground inspection was conducted on September 9, 2025. Violation confirmed corrected by letter received from provider on 3/31/2026

● **The Depth of the Loose Surfacing Was Not Based on Critical Height of the Equipment.**

The depth of the mulch around the slides and swings on all three (3) playgrounds measured 4 inches, instead of the required six inches. Violation confirmed corrected by letter received from provider on

Oct 9, 2025 3 Findings ● 3 Important

● **All Walls and Ceilings Including Doors and Windows Were Not Kept Clean, Free of Visible Fungal Growth, and in Good Repair.**

Space 4 had chipping paint on four(4) walls and one window sill. In Space 6, there were two pieces of molding that were loose on the wall near edge of the carpet.

● **Equipment and Furnishings Were Not Sturdy, Stable and Free of Hazards.**

On the playground for children age two years, there were eight(8) "S" hooks on the swings that need to be closed. On the infant/toddler playground, there were two pieces of red, metal, equipment that had chipping p

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.

- **All Equipment and Furnishings Were Not in Good repair.In Space 1, There Was a Vinyl Mat with Areas of Vinyl Pieces That Were Flaking.**

This was removed during the visit. In Space 4, there was a sink cabinet that had chipping paint. In Space 5, there was a bucket of small chalk pieces t

About this report

Childery generates this report from public inspection records published by the North Carolina Division of Child Development and Early Education. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the North Carolina Division of Child Development and Early Education.