

Ashley, Richele

223-31 110TH AVENUE
QUEENS VILLAGE, NY

1 Inspection Visit Since 2026 - 3 Findings - 100% Corrected at Visit

Most recent inspection: Mar 18, 2026

● 3 Important

Across 1 inspection since 2026, the issues cited most often were There Must Be an Operational Smoke Detector on Each Floor of the Home. (2) and Porches, Decks or Stairs with More Than Two Steps Must Have Railings with a Barrier Extending to the Floor or Ground to Prevent Children From Falling. Acceptabl (1). None of the 3 findings were critical.

Inspection Visits

Mar 18, 2026 3 Findings ● 3 Important

- **There Must Be an Operational Smoke Detector on Each Floor of the Home.**

416.4(c)

Corrected at visit

- **Multi-purpose Fire Extinguishers of a Type Approved for Use in Residences Must Be Maintained in Good Working Condition and Placed in the Kitchen and Outside The**

416.4(f)

Corrected at visit

- **Porches, Decks or Stairs with More Than Two Steps Must Have Railings with a Barrier Extending to the Floor or Ground to Prevent Children From Falling. Acceptabl**

416.5(e)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.