

BestSelf Behavioral Health, Inc.

325 Manhattan Avenue
Buffalo, NY

4 Inspection Visits Since 2025 - 5 Findings - 100% Corrected at Visit

Most recent inspection: Feb 4, 2026

● 5 Important

Across 4 inspections since 2025, the issues cited most often were All Fire Suppression Equipment and Systems Must Be Tested and Maintained in Accordance with the Applicable Requirements of the Fire Code and Building Code of Ne (4) and Play Equipment Must Be Installed and Used in Accordance with the Manufacturer's Specifications and Instructions, Be in Good Repair, and Be Placed in a Safe Loca (1). None of the 5 findings were critical.

Inspection Visits

Feb 4, 2026 1 Finding ● 1 Important

- **All Fire Suppression Equipment and Systems Must Be Tested and Maintained in Accordance with the Applicable Requirements of the Fire Code and Building Code of Ne**

414.4(e)

Corrected at visit

Sep 24, 2025 2 Findings ● 2 Important

- **Evacuation Drills Must Be Conducted at Least Monthly During Various Hours of Operation of the School Age Child Care Program.**

414.4(b)(1)

Corrected at visit

- **The Director or a Designated Qualified Staff Member Must Conduct Monthly Inspections of the Premises to Observe Possible Fire and Safety Hazards. Any Such Hazar**

414.4(h)

Corrected at visit

May 15, 2025 1 Finding ● 1 Important

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.

- **The Director or a Designated Qualified Staff Member Must Conduct Monthly Inspections of the Premises to Observe Possible Fire and Safety Hazards. Any Such Hazard**

414.4(h)

Corrected at visit

Apr 22, 2025 1 Finding ● 1 Important

- **Play Equipment Must Be Installed and Used in Accordance with the Manufacturer's Specifications and Instructions, Be in Good Repair, and Be Placed in a Safe Location**

414.5(n)(2)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.