

Tsl Daycare

183 School House Road
Albany, NY

3 Inspection Visits Since 2026 · 5 Findings · 0% Corrected at Visit

Most recent inspection: May 27, 2026

● 5 Important

Across 3 inspections since 2026, the issues cited most often were Fire Detection, Alarm and Firefighting Equipment Appropriate to the Type of Building Construction, Size, Height and Occupancy Must Be Provided Maintained and Op (2), The Program Must Maintain on File at the Program, Available for Inspection by the Office or Its Designees at Any Time, the Following Records in a Current and Ac (1), and Children Cannot Be Left Without Competent Direct Supervision at Any Time. Competent Supervision Includes Awareness of and Responsibility for the Ongoing Activit (1). None of the 5 findings were critical.

Inspection Visits

May 27, 2026 1 Finding ● 1 Important

- **The Program Must Maintain on File at the Program, Available for Inspection by the Office or Its Designees at Any Time, the Following Records in a Current and Ac**
414.15(c)(5)

May 22, 2026 1 Finding ● 1 Important

- **Children Cannot Be Left Without Competent Direct Supervision at Any Time. Competent Supervision Includes Awareness of and Responsibility for the Ongoing Activit**
414.8(a)

Feb 18, 2026 3 Findings ● 3 Important

- **Fire Detection, Alarm and Firefighting Equipment Appropriate to the Type of Building Construction, Size, Height and Occupancy Must Be Provided Maintained and Op**
414.4(c)
- **All Corridors, Aisles, and Approaches to Exits Must Be Kept Unobstructed at All Times.**
414.4(f)(2)

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.

- **Glass in Outside Windows Less Than 32 Inches Above the Floor Level Must Be of Safety Grade or Otherwise Protected by Use of Barriers to Avoid Accidental Impact.**

414.5(p)

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.