

# Hopes Little Blessings LLC

110-15 178th Street  
Saint Albans, NY

## 1 Inspection Visit Since 2024 · 3 Findings · 100% Corrected at Visit

Most recent inspection: Jun 14, 2024

● 3 Important

Across 1 inspection since 2024, the issues cited most often were There Must Be an Operational Smoke Detector on Each Floor of the Home. (2) and Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard. (1). None of the 3 findings were critical.

## Inspection Visits

**Jun 14, 2024** 3 Findings ● 3 Important

● **There Must Be an Operational Smoke Detector on Each Floor of the Home.**

416.4(c)

Corrected at visit

● **All Paths of Egress on the Interior and Exterior of the Home, Including Corridors, Aisles and Approaches Must Be Kept Free of Obstructions, Impediments and Debr**

416.4(h)(4)

Corrected at visit

● **Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard.**

416.5(a)

Corrected at visit

### About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.