

Wonder Clubhouse Inc.

372 West 127th Street
New York, NY

2 Inspection Visits Since 2025 · 4 Findings · 75% Corrected at Visit

Most recent inspection: Mar 24, 2026

● 4 Important

Across 2 inspections since 2025, the issues cited most often were The Clearances Required Pursuant to This Section, Other Than Those for Which On-going Criminal History Results Are Provided, Shall Be Conducted for Any Existing (1), Peeling or Damaged Paint or Plaster Must Be Repaired. (1), and In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case (1). None of the 4 findings were critical.

Inspection Visits

Mar 24, 2026 1 Finding ● 1 Important

- **The Clearances Required Pursuant to This Section, Other Than Those for Which On-going Criminal History Results Are Provided, Shall Be Conducted for Any Existing**
413.4(d)(4)

Mar 4, 2025 3 Findings ● 3 Important

- **Peeling or Damaged Paint or Plaster Must Be Repaired.**
416.3(h)
Corrected at visit
- **In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case**
416.4(d)
Corrected at visit
- **The Emergency Evacuation Diagram Must Be Posted in a Visible Location.**
416.5(b)(2)
Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.