

Millennium Development

1925 Stuart St
Brooklyn, NY

2 Inspection Visits Since 2024 - 3 Findings - 100% Corrected at Visit

Most recent inspection: Feb 13, 2025



● 3 Important

Across 2 inspections since 2024, the issues cited most often were All Clearances Required Pursuant to Subdivision (A) of This Section; And (1), Peeling or Damaged Paint or Plaster Must Be Repaired. (1), and Windows Above the First Floor That Are Accessible to Children and Present a Fall Hazard Must Be Protected by Permanent Barriers or Restrictive Locking Devices T (1). None of the 3 findings were critical.

Inspection Visits

Feb 13, 2025 1 Finding ● 1 Important

- **All Clearances Required Pursuant to Subdivision (A) of This Section; And 413.4(b)(1)**

Corrected at visit

Oct 2, 2024 2 Findings ● 2 Important

- **Peeling or Damaged Paint or Plaster Must Be Repaired.**
414.3(g)
- **Windows Above the First Floor That Are Accessible to Children and Present a Fall Hazard Must Be Protected by Permanent Barriers or Restrictive Locking Devices T**
414.5(q)

Corrected at visit

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.