

Sentino, Cara

535 Hinsdale Street
Brooklyn, NY

1 Inspection Visit Since 2025 - 2 Findings - 0% Corrected at Visit

Most recent inspection: Dec 10, 2025

● 2 Important

Across 1 inspection since 2025, the issues cited most often were In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case (1) and Operating Carbon Monoxide Detectors Must Be Used in All Family Day Care Homes When Required, and Located in Areas of the Home in Accordance with Applicable Laws (1). None of the 2 findings were critical.

Inspection Visits

Dec 10, 2025 2 Findings ● 2 Important

- **In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case**
417.4(d)
- **Operating Carbon Monoxide Detectors Must Be Used in All Family Day Care Homes When Required, and Located in Areas of the Home in Accordance with Applicable Laws**
417.5(v)

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.