

Herkimer Reformed Church

102 Church Street
Herkimer, NY

1 Inspection Visit Since 2025 · 3 Findings · 100% Corrected at Visit

Most recent inspection: May 7, 2025

● 3 Important

Across 1 inspection since 2025, the issues cited most often were Suitable Precautions Must Be Taken to Eliminate All Conditions Which May Contribute to or Create a Fire Hazard. (3). None of the 3 findings were critical.

Inspection Visits

May 7, 2025 3 Findings ● 3 Important

- **Suitable Precautions Must Be Taken to Eliminate All Conditions Which May Contribute to or Create a Fire Hazard.**

414.4(a)

Corrected at visit

- **All Fire Suppression Equipment and Systems Must Be Tested and Maintained in Accordance with the Applicable Requirements of the Fire Code and Building Code of Ne**

414.4(e)

Corrected at visit

- **All Corridors, Aisles, and Approaches to Exits Must Be Kept Unobstructed at All Times.**

414.4(f)(2)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.