

# APPLE OF MY EYES

1228 Rosedale ave  
Bronx, NY

## 1 Inspection Visit Since 2025 - 3 Findings - 100% Corrected at Visit

Most recent inspection: Jul 10, 2025

● 3 Important

Across 1 inspection since 2025, the issues cited most often were In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case (2) and Protective Caps, Covers or Permanently Installed Obstructive Devices Must Be Used on All Electrical Outlets That Are Accessible to Children. (1). None of the 3 findings were critical.

## Inspection Visits

**Jul 10, 2025** 3 Findings ● 3 Important

- **In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case**

416.4(d)

Corrected at visit

- **All Paths of Egress on the Interior and Exterior of the Home, Including Corridors, Aisles and Approaches Must Be Kept Free of Obstructions, Impediments and Debr**

416.4(h)(4)

Corrected at visit

- **Protective Caps, Covers or Permanently Installed Obstructive Devices Must Be Used on All Electrical Outlets That Are Accessible to Children.**

416.5(i)

Corrected at visit

### About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.