

Mancebo Sanchez, Manuel

27 Sickles Street
New York, NY

3 Inspection Visits Since 2024 · 3 Findings · 100% Corrected at Visit

Most recent inspection: Oct 8, 2025

● 3 Important

Across 3 inspections since 2024, the issues cited most often were In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case (2) and Clear Interior or Exterior Glass Doors Must Be Marked Clearly to Avoid Accidental Impact. (1). None of the 3 findings were critical.

Inspection Visits

Oct 8, 2025 1 Finding ● 1 Important

- In Addition to a Smoke Detector on Each Floor, There Must Be a Smoke Detector Located Either Within Rooms Where Children Nap, or in Adjoining Rooms. In the Case

416.4(d)

Corrected at visit

Jul 1, 2025 1 Finding ● 1 Important

- Clear Interior or Exterior Glass Doors Must Be Marked Clearly to Avoid Accidental Impact.

416.5(o)

Corrected at visit

Oct 7, 2024 1 Finding ● 1 Important

- All Paths of Egress on the Interior and Exterior of the Home, Including Corridors, Aisles and Approaches Must Be Kept Free of Obstructions, Impediments and Debr

416.4(h)(4)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.