

Cabrera, Esmirna

52-54 Saint Nicholas Place
New York, NY

2 Inspection Visits Since 2025 · 4 Findings · 100% Corrected at Visit

Most recent inspection: Dec 30, 2025

● 4 Important

Across 2 inspections since 2025, the issues cited most often were Peeling or Damaged Paint or Plaster Must Be Repaired. (2) and Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard. (2). None of the 4 findings were critical.

Inspection Visits

Dec 30, 2025 1 Finding ● 1 Important

● **Peeling or Damaged Paint or Plaster Must Be Repaired.**

417.3(h)

Corrected at visit

Jan 27, 2025 3 Findings ● 3 Important

● **Peeling or Damaged Paint or Plaster Must Be Repaired.**

417.3(h)

Corrected at visit

● **Suitable Precautions Must Be Taken to Eliminate All Conditions in Areas Accessible to Children Which Pose a Safety or Health Hazard.**

417.5(a)

Corrected at visit

● **Protective Caps, Covers or Permanently Installed Obstructive Devices Must Be Used on All Electrical Outlets That Are Accessible to Children.**

417.5(i)

Corrected at visit

About this report

Childery generates this report from public inspection records published by the New York State Office of Children and Family Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the New York State Office of Children and Family Services.