

STONEWALL HEADSTART

600 S HIGHSCHOOL AVE
STONEWALL, OK

5 Inspection Visits Since 2024 · 1 Finding

Most recent inspection: Feb 18, 2026



● 1 Important

Across 5 inspections since 2024, the issues cited most often were Fire Extinguishers Last Serviced September 2023. (1). The single finding was not critical.

Inspection Visits

Dec 4, 2024 1 Finding ● 1 Important

● **Fire Extinguishers Last Serviced September 2023.**

Periodic - Full

About this report

Childery generates this report from public inspection records published by the Oklahoma Department of Human Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Oklahoma Department of Human Services, Child Care Services.