

SNICKLEFRITZ SOUTH

414 N Cliff Avenue
Harrisburg, SD

9 Inspection Visits Since 2025 · 22 Findings

Most recent inspection: Apr 22, 2026



● 22 Important

Across 9 inspections since 2025, the issues cited most often were The program's utility closet contained an excess of stored items, preventing the required three feet of clearance around the electrical panel and HVAC units. At the time of the inspection, a carbon monoxide detector could not be located. (2), At the time of the inspection, not all provider information was available to review. (2), and Cited rule (1). None of the 22 findings were critical.

Inspection Visits

Apr 22, 2026 1 Finding ● 1 Important

- The program's utility closet contained an excess of stored items, preventing the required three feet of clearance around the electrical panel and HVAC units. At the time of the inspection, a carbon monoxide detector could not be located.

67:42:17:32 - 67:42:17:32 All walls, ceilings, floors, and equipment must be easily cleanable, kept clean, and in good repair. Heating and cooling systems must maintain a temp...

Apr 16, 2026 3 Findings ● 3 Important

- Cited rule
61:15:01:01 - In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 inches below sprinkler head deflectors? 61:15:01:01
- Cited rule
61:15:01:01 - Is there a carbon monoxide detector installed according to the manufacturer's directions if there is a furnace or appliances utilizing fossil fuels such as propane...
- Cited rule
67:42:17:31 - Is food, including breast milk and formula, properly stored, kept at the proper temperature, and protected from potential contamination? 67:42:17:31 NOTE: Refr...

Mar 26, 2026 3 Findings ● 3 Important

About this report

Childery generates this report from public inspection records published by the South Dakota Department of Social Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the South Dakota Department of Social Services, Child Care Services.

- **Atthetimeoftheinspection,notallproviderinformationwasavailabletoreview.**
67:42:17:15 - 67:42:17:15 Achildcareprovidershallmaintainarecordforeachemployeeethatincludes: (1) Theemployee'sname-anddateofbirth; (2) Thedatesonwhichtheem...
- **Theprogramdidnotobtainwrittenconsenttoadministermedicationforallmedicinesinitssession. TheEpiPensprovidedbyparentsdidnotincludethemedication'soriginallabel.**
67:42:17:27 - 67:42:17:27 Beforeanymedicationisadministeredtoachild,permissionoftheparentorguardianmustbedocu-mentedandmust includethenameofthechild,thenam...
- **Duringthevisit,providerswerenotabletoreadilyexplaintheprogram'semergencypreparednessandrespon- seplan Procedures.**
67:42:17:43 - 67:42:17:43 Aprovidershallhave: (1) Awrittenemergencypreparednessandresponseplanforemergenciesresult- ingfromanaturaldisasteroraman- causedeve...

Mar 19, 2026 4 Findings ● 4 Important

- **Cited rule**
67:42:17:15 - Doemployeerecordscontainallrequiredinformation?67:42:17:15
- **Cited rule**
67:42:17:27 - Aremedicationsprovidedbytheparentkeptintheiroriginalcontainerwiththeoriginallabel? Forprescriptionmedica- tions,doesthelabelincludethechild'sn...
- **Cited rule**
67:42:17:27 - Iswrittenconsentobtainedfromeachchild'sparentbeforeadministeringallprescriptionand non-prescriptionmed- ication?Doestheconsentincludethechild'...
- **Cited rule**
67:42:17:45 - Iftransportationisprovided,doestheprogramhaveproofoffiabilityinsuranceforthe vehicle(s)usedtotransportchil- dren?67:42:17:45 Yes Comments Addi...

Jan 22, 2026 2 Findings ● 2 Important

- **DuringacomplaintinvestigationconductedbytheOfficeofLicensing&Accreditation,itwasconfirmedthat- achild Underoneyearofagewasleftunsupervisedintheclassroomwhilesleeping.**
67:42:17:20 - 67:42:17:20 1 Acenterprovidersupervisingchildrenmustbeinthesameroomwiththechildrenorontheplayground- withthe children,andmustbeabletoseeorhear...

About this report

Childery generates this report from public inspection records published by the South Dakota Department of Social Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the South Dakota Department of Social Services, Child Care Services.

- **During a complaint investigation conducted by the Office of Licensing & Accreditation, it was confirmed that a child under one year of age was allowed to sleep in a bouncy seat, which is not an approved sleep practice under Caring for Our Children: National Health and Safety Performance Standards.**
67:42:17:26 - 67:42:17:26 A nap mat, blanket, or other sleep surface, other than the floor, for children over one year of age must be available for each child during naptime. Asle...

Jun 24, 2025 2 Findings ● 2 Important

- **During the program inspection conducted on June 3, 2025, by the Office of Licensing and Accreditation, while reviewing The staff files, several providers were found to be missing the required documentation.**
67:42:17:15 - 67:42:17:15 A child care providers shall maintain a record for each employee that includes: (1) The employee's name and date of birth; (2) The dates on which the em...
- **During the program inspection conducted on June 3, 2025, by the Office of Licensing and Accreditation, while reviewing The child files, it was found that several children were missing the required documentation.**
67:42:17:42 - 67:42:17:42 A providers shall maintain a record for each child that includes: (1) The child's name and date of birth; (2) The parent or guardian's name and telepho...

Jun 2, 2025 2 Findings ● 2 Important

- **Cited rule**
67:42:17:15 - Do employee records contain all required information? 67:42:17:15
- **Cited rule**
67:42:17:45 - If transportation is provided, does the program have proof of liability insurance for the vehicle(s) used to transport children? 67:42:17:45...

Apr 24, 2025 2 Findings ● 2 Important

- **The HVAC inspection report was not available at the time of the inspection.**
67:42:17:32 - 67:42:17:32 All walls, ceilings, floors, and equipment must be easily cleanable, kept clean, and in good repair. Heating and cooling systems must maintain a temp...
- **The fire alarm and fire extinguisher maintenance report was Unavailable during the inspection. A carbon monoxide detector was not located during the inspection.**
67:42:17:37 - 67:42:17:37 Center and school-age programs operating outside of a school building shall follow applicable construction and fire safety requirements, as outlined...

About this report

Childery generates this report from public inspection records published by the South Dakota Department of Social Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the South Dakota Department of Social Services, Child Care Services.

Mar 19, 2025 3 Findings  3 Important

● **Cited rule**

61:15:01:01 - In Licensed Programs caring for 21 or More Children - Is a fire alarm system inspected and serviced annually by a qualified service technici...

● **Cited rule**

67:42:17:24 - Is each child provided individual space for personal items to prevent the spread of an infestation or infectious disease? 67:42:17:24 Yes Wh...

● **Cited rule**

67:42:17:31 - protected from potential contamination? 67:42:17:31 NOTE: Refrigerator temperature should be maintained at 41 degrees F or below, and the fr...

About this report

Childery generates this report from public inspection records published by the South Dakota Department of Social Services, Child Care Services. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the South Dakota Department of Social Services, Child Care Services.