

Texas Spanish Academy

2050 DOUBLE CREEK DR STE 109
ROUND ROCK, TX

2 Inspection Visits Since 2025 · 3 Findings

Most recent inspection: Dec 5, 2025



● 2 Critical ● 1 Important

Across 2 inspections since 2025, the issues cited most often were Installation and Maintenance of Loose-fill Surfacing - Posts Marked to Proper Depth (1), Maintenance Procedures for Active Play - Hazards Removed or Repaired (1), and No Blocked or Locked Doors as Exits (1). Of 3 total findings, 2 were critical.

Inspection Visits

Dec 5, 2025 2 Findings ● 1 Critical ● 1 Important

● **Maintenance Procedures for Active Play - Hazards Removed or Repaired**
746.4751(c)

● **Installation and Maintenance of Loose-fill Surfacing - Posts Marked to Proper Depth**
746.4907(c)

Sep 9, 2025 1 Finding ● 1 Critical

● **No Blocked or Locked Doors as Exits**
746.5209(c)

About this report

Childery generates this report from public inspection records published by the Texas Health and Human Services Commission. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Texas Health and Human Services Commission.