

Wooden After The Bell

200 LOUISE RITTER BLVD
RED OAK, TX

1 Inspection Visit Since 2025 · 1 Finding

Most recent inspection: Nov 7, 2025

● 1 Important

Across 1 inspection since 2025, the issues cited most often were Electronic CO Detection Sys Connected to Alarm/Smoke Detection Sys-Test Documentation Includes Inspector's Name, Phone Number, and Test Date (1). The single finding was not critical.

Inspection Visits

Nov 7, 2025 1 Finding ● 1 Important

- **Electronic CO Detection Sys Connected to Alarm/Smoke Detection Sys-Test Documentation Includes Inspector's Name, Phone Number, and Test Date**
744.3757(b)(3)

About this report

Childery generates this report from public inspection records published by the Texas Health and Human Services Commission. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Texas Health and Human Services Commission.