

EPIC

701 SUPERIOR LANCE
YAKIMA, WA

1 Inspection Visit Since 2026 - 3 Findings

Most recent inspection: Apr 22, 2026

● 3 Important

Across 1 inspection since 2026, the issues cited most often were 0145(5) The Small Out Door Play Area Had a 5 Inch Gab Under the Chain Link Fencing. (1), 0166(3)(a) The Emergency Exit Door Next to Class Room #1 Was Not Working and Could Not Open. (1), and 0260(1)(a) The Mechanical Room Was Unlocked with Sta-Flo and Oxivir and Other Cleaning Products Labeled Keep Out of Reach of Children. Staff Members Locked Door Onsite. (1). None of the 3 findings were critical.

Inspection Visits

Apr 22, 2026 3 Findings ● 3 Important

● **0145(5) The Small Out Door Play Area Had a 5 Inch Gab Under the Chain Link Fencing.**

110-300-0145(8) - Fences, barriers, and gates must be in good condition, have no gap through which a sphere with a diameter of three and one-half inches can pass, and have a mini...

● **0166(3)(a) The Emergency Exit Door Next to Class Room #1 Was Not Working and Could Not Open.**

Serious: 110-300-0166(3) - Page 2 of 4 Non-Compliances: This section of the Inspection Report lists non-compliances found during any licensing inspection. Information from this section wi...

● **0260(1)(a) The Mechanical Room Was Unlocked with Sta-Flo and Oxivir and Other Cleaning Products Labeled Keep Out of Reach of Children. Staff Members Locked Door Onsite.**

Serious: 110-300-0260(1) - An early learning provider must ensure all poisonous or dangerous substances including, but not limited to fuels, solvents, oils, laundry, dishwasher, other det...

About this report

Childery generates this report from public inspection records published by the Washington State Department of Children, Youth, and Families, Licensing Division. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Washington State Department of Children, Youth, and Families, Licensing Division.