

SPOONER HEAD START

851 NORTHLAND DR
SPOONER, WI

1 Inspection Visit Since 2025 · 2 Findings

Most recent inspection: Apr 4, 2025



● 2 Important

Across 1 inspection since 2025, the issues cited most often were Outdoor Play Equipment - Construction, Condition (1) and 251.06(11)(bm)3. (1). None of the 2 findings were critical.

Inspection Visits

Apr 4, 2025 2 Findings ● 2 Important

● **Outdoor Play Equipment - Construction, Condition**

251.06(11)(bm)3.

The black plastic borders surrounding the play equipment and for maintaining the energy absorbing surfaces had protrudi

● **251.06(11)(bm)3.**

Rule Number

Rule Summary

About this report

Childery generates this report from public inspection records published by the Wisconsin Department of Children and Families, Bureau of Early Care Regulation. Childery did not conduct these inspections or produce the original state reports. Childery is an independent directory and is not affiliated with the Wisconsin Department of Children and Families, Bureau of Early Care Regulation.